

ConvertMate - Pressure Conversion Reference Chart

Source unit: bar

bar	psi	kilopascals	pascals	atmospheres
0.5	7.2519	50.0000	50000.0000	0.4935
1	14.5038	100.0000	100000.0000	0.9869
1.5	21.7557	150.0000	150000.0000	1.4804
2	29.0076	200.0000	200000.0000	1.9738
3	43.5114	300.0000	300000.0000	2.9608
4	58.0152	400.0000	400000.0000	3.9477
5	72.5190	500.0000	500000.0000	4.9346
10	145.0380	1000.0000	1000000.0000	9.8692
15	217.5570	1500.0000	1500000.0000	14.8038

Printable quick-reference chart - free online at convertmate.xyz